

C I P E J C I
JUN 8 2 2005
PATENT & TRADEMARK OFFICE
ACTUATING HANDLE ASSEMBLY
Bancroft et al
10/764,616
Replacement Sheet

1/7





FIG. 1

ACTUATING HANDLE ASSEMBLY
Bancroft et al
10/764,616
Replacement Sheet

2/7



ACTUATING HANDLE ASSEMBLY
Bancroft et al
10/764,616
Replacement Sheet

3/7

FIG. 3A





FIG. 3B



ACTUATING HANDLE ASSEMBLY
Bancroft et al
10/764,616
Replacement Sheet

4/7

FIG. 4A






FIG. 4B




ACTUATING HANDLE ASSEMBLY
Bancroft et al
10/764,616
Replacement Sheet

5/7



ACTUATING HANDLE ASSEMBLY
Bancroft et al
10/764,616
Replacement Sheet

6/7



ACTUATING HANDLE ASSEMBLY
Bancroft et al
10/764,616
Replacement Sheet

7/7





FIG. 8